

## Ector Drum, Inc.

### Photo Log

Description: View of site from N. Marco Avenue.

Category: Site Photo

Latitude:

Date Taken: 5/21/2015

Longitude:

Tags:



Description: Additional view of site from N. Marco Avenue.

Category: Site Photo

Latitude:

Date Taken: 5/21/2015

Longitude:

Tags:



Description: View of site from intersection of N. Marco Avenue and E. Market Street

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of sign posted on front door to office building located on N. Marco street.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of gate entrance located on south side of site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



500010256

## Ector Drum, Inc.

### Photo Log

Description: View of trough at Drum Unloading Platform; contains standing liquid

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of drums inside the south building

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of drums between south building and secondary containment for Above-ground Storage tanks.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of three ASTs in secondary containment area,. Notice liquid and drums inside secondary containment

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of well, well tank, and secondary containment surrounding the well inside the well house.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



## Ector Drum, Inc.

### Photo Log

Description: View of drums inside the north section of the AST secondary containment.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of AST labeled "Hazardous Waste" inside the AST secondary containment.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of ASTs 2 and 3 located in AST secondary containment area. Notice drums and standing liquid inside secondary containment

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of material inside drum located in south building.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: Various containers located on south side of the site.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



## Ector Drum, Inc.

---

### Photo Log

---

Description: View of drums located in in southeast section of site.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of drums in east section of site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of drums in central section of site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of 350-gallon tote containers located in southeast section of site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of oil well located in east section of site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:





## Ector Drum, Inc.

### Photo Log

Description: Drums located in center section of site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of drums and tar mats located in center section of site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of sheen on standing liquid in the center section of the site.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of additional drums and five gallon plastic containers

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of stacked 350-gallon totes located in the north section of the site

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



## Ector Drum, Inc.

---

### Photo Log

---

Description: View of cracks in the AST secondary containment system. Notice oily liquid inside secondary containment area

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of 350-gallon tote that is 3/4 full with a liquid material. Located in north section of site.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of Drum Unloading Platform located east of the south building.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of standing liquid underneath the Drum Unloading Platform

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



## Ector Drum, Inc.

### Photo Log

Description: View of two Underground Storage Tanks (USTs) located along the south fence line.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of gate entrance located in southeast section of site. Opening in gate will allow access to site.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of dead coyote located in the southeast section of the site.

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: 55-gallon poly drum in southeast section of site labeled as Flammable Liquid N.O.S.; UN1993

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: Labeled 350-gallon tote that was located in southeast section of site and sampled/hazcatted.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



## Ector Drum, Inc.

---

### Photo Log

---

Description: View of label on a 55-gallon poly drum located at the site.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: Container inside metal basket located inside south building; labeled as Flammable Liquid, N.O.S., Contains Benzene & Carbon Bisulfide; Endura Products Corp, Midland, TX

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: 55-gallon steel drum inside south building labeled as "Dixichlor".

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of 55-gallon poly drum labeled as "Corrosive Liquid N.O.S., Zinc Chloride", Corrosion LTD. Hobbs, NM"

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:





## Ector Drum, Inc.

### Photo Log

Description: View of soil sampling at station EDS-01, in southeast, offsite drainage pathway.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of sampling station EDS-02 located in the south section of the site, near the gate entrance.

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of soil sampling station EDS-03, located inside the south building, along the south wall

Category: Site Photo

Latitude:

Date Taken: 5/19/2015

Longitude:

Tags:



Description: View of sampling/hazcatting a 350-gallon tote located in the southeast section of the site.

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of sampling/hazcatting a 55-gallon poly drum located in southeast section of site.

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



## Ector Drum, Inc.

---

### Photo Log

---

Description: View of sampling/hazcatting a 350-gallon tote located in the north section of the site.

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of sampling/hazcatting a 55-gallon poly drum located between the AST secondary containment area and the south building

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of sampling/hazcatting a second 55-gallon poly drum in area between south building and AST secondary containment area

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of sampling/hazcatting at station EDL-10, inside south building

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



## Ector Drum, Inc.

---

### Photo Log

---

Description: View of sample station EDL-08, the trough associated with the Drum Unloading Platform.

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of sample station EDL-08, the AST secondary containment area.

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of soil sample station EDS-04, located on the southeast corner of the AST secondary containment area

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Description: View of soil sample station EDS-05/07, located in the central section of the site.

Category: Site Photo

Latitude:

Date Taken: 5/20/2015

Longitude:

Tags:



Ector Drum, Inc.

Photo Log

Description: View o soil sampling station EDS-06, located in the central section of the site.

Category: Site Photo Latitude:

Date Taken: 5/20/2015 Longitude:

Tags:

